IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicant:

XIAO

Patent No:

7,392,770

Serial No.:

10/577339

Issue Date:

July 1, 2008

Filed:

April 27, 2006

Docket No.:

09548.1028USWO

Title:

A COOLING SYSTEM OF AN ENGINE FOR THE INSIDE OF A

GENERATOR

CERTIFICATE OF TRANSMISSION

I hereby certify that this paper is being transmitted by EFS Web to: Commissioner for Palent

on February 4, 2009.

Name: Lauren, Sindt

REQUEST FOR CERTIFICATE OF CORRECTION

Attn: Certificate of Correction Branch

Commissioner for Patents

P.O. Box 1450

Alexandria, Virginia 22313-1450

Dear Sir:

It is requested that a Certificate of Correction be issued correcting printing errors appearing in the above-identified United States patent. A copy of the text of the Certificate in the suggested form is attached.

Issuance of the Certificate of Correction would neither expand nor contract the scope of the claims, and re-examination is not required.

As none of the errors are the Patentees' mistake, it is believed that no fee is due.

Respectfully submitted,

52835

PATENT TRADEMARK OFFICE

HAMRE, SCHUMANN, MUELLER & LARSON, P.C. P.O. Box 2902 Minneapolis, MN 55402-0902

(612) 455/3800

Dated: February 4, 2009

Rong Yang

Lim. Recognition No.: L0279

CY/ls

PTO/SB/44 (09-07)

Approved for use through 08/31/2010. OM8 0851-0033

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

CERTIFICATE OF CORRECTION
Page <u>1</u> of <u>1</u> PATENT NO. : 7,392,770 B2
APPLICATION NO.: 10/577339
ISSUE DATE : July 1, 2008
INVENTOR(S) : Henglin Xiao
It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:
Column 2, line 1: "technology in the art the" should readtechnology in the art, the Column 3, line 4: "said tool air suction hood" should readsaid cool air suction hood Column 4, line 10: "manufacturing cost The engine" should readmanufacturing cost. The engine Column 4, line 49: "a scaling ring sealing a connection" should reada sealing ring sealing a connection Column 6, line 9 (claim 7): "magnet motor the cool" should readmagnet motor, the cool

MAILING ADDRESS OF SENDER (Please do not use customer number below):

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.